



5611 Hollister Ave.
Goleta, California
93117
(805) 967-5611
SERVICE LINE: 683-2593

THE TOYOTA TOUCH
Service Excellence Award

CUSTOMER NO. 42065	ADVISOR DOUG KURZ	HAT NO. 409	INVOICE DATE 05/12/05	INVOICE NO. T0CS202118
PETER MAIVALD	LICENSE NO. JEZDEC	MILEAGE 121142	COLOR SILVER/	STOCK NO.
2927 SELWYN CIRCLE	YEAR / MAKE / MODEL 01/TOYOTA/CELICA	DELIVERY DATE	DELIVERY MILES	
SANTA BARBARA, CA 93105	VEHICLE ID. NO. JTDDR32T010104764	SELLING DEALER NO.	PRODUCTION DATE 05/01/01	
RESIDENCE PHONE 456-3810	F.T.E. NO.	P.O. NO.	R.O. DATE 05/10/05	
BUSINESS PHONE	COMMENTS			

THIS CHECK-UP IS NOT A COMPLETE CHECK OF EVERY COMPONENT OF THE VEHICLE. DEALER DOES NOT IMPLY A WARRANTY OF FITNESS FOR ANY INSPECTED OR UNINSPECTED COMPONENT OF THE VEHICLE.

LABOR & PARTS-----
J# 1 01TOZMAJOR COUPON MAJOR SERVICE TECH(S):DR00 208.86
LOF, BRAKE SERVICE, ROTATE TIRES, REPLACE AIR FILTER
TRANS SERV, TUNE, FLUSH COOLANT, BAT SERVICE, 20 PT INSPECT
LUBE, OIL, FILTER CHANGE.
BATTERY SERVICE/LOAD TEST
CHECK SPARE TIRE PSI
LUBE, OIL AND FILTER CHANGE, SERVICED AND ADJUSTED BRAKES,
ROTATED TIRES, REPLACED AIR FILTER, SERVICED
TRANSMISSION, FLUSHED COOLING SYSTEM AND PRESSURE CHECKED
FOR LEAKS, TUNED ENGINE, AND COMPLETE INSPECTION.

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 1	1		90915-YZZA1	FILTER S/A, OIL	6.00	6.00
JOB # 1	1		90430-12031	GASKET	0.95	0.95
JOB # 1	1		BRK	BRAKE CLEAN	3.00	3.00
JOB # 1	1		00272-1LLAC	TOYOTA COOLANT	18.87	18.87
JOB # 1	1		17801-16020-83	ELEMENT S/A, FILTE	18.95	18.95
JOB # 1	4		90919-01217	PLUG, SPARK	17.83	71.32
JOB # 1 TOTAL PARTS						119.09
JOB # 1 TOTAL LABOR & PARTS						327.95

J# 2+02TOZBELTS BELTS TECH(S):DR00 79.00
TECH NOTES DRIVERBELT BADLY CRACKED
REMOVED AND REPLACED DRIVERBELT

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 2	1		90916-02534	BELT, V-RIBBED	68.72	68.72
JOB # 2 TOTAL PARTS						68.72
JOB # 2 TOTAL LABOR & PARTS						147.72

J# 3+81TOZHEAD HEAD LITE TECH(S):DR00 39.50
TECH NOTES THAT LEFT LOW BEAM HEADLITE IS INOP
REMOVED AND REPLACED LEFT LOW BEAM HEADLIGHT BULB, OK AT
THIS TIME

PARTS	QTY	FP	NUMBER	DESCRIPTION	UNIT PRICE	
JOB # 3	1		90981-13063	BULB	47.66	47.66
JOB # 3 TOTAL PARTS						47.66
JOB # 3 TOTAL LABOR & PARTS						87.16

G.O.G. & SUPPLIES-----
JOB # 1 1.0 3 QT TRANSMISSION SPECIAL @ 5.000 /UNIT 5.00
JOB # 1 1.0 5 QT OIL CHANGE SPECIAL @ 9.000 /UNIT 9.00
TOTAL - GOG 14.00

ESTIMATE-----
CUSTOMER HEREBY ACKNOWLEDGES RECEIVING
ORIGINAL ESTIMATE OF \$341.95 (+TAX)
APPROVED REVISED ESTIMATE (# 1) OF \$577.95 (+TAX) ON 05/10/05 AT 04:00pm
BY MAIVALD COMMENTS HEADLIGHT BULB, DRIVEBELT
COMMENTS-----
FRONT BRAKES HAVE 7.5MM REMAINING
REAR BRAKES HAVE 3MM REMAINING



5611 Hollister Ave.
Goleta, California
93117
(805) 967-5611
SERVICE LINE: 683-2593

THE TOYOTA TOUCH
Service Excellence Award

CUSTOMER NO. 42065	ADVISOR DOUG KURZ	409	HAT NO.	INVOICE DATE 05/12/05	INVOICE NO. 10C5202118
PETER MAIVALD	LICENSE NO. JEZDEC	MILEAGE 121142	COLOR SILVER/	STOCK NO.	
2927 SELWYN CIRCLE	YEAR / MAKE / MODEL 01/TOYOTA/CELICA	DELIVERY DATE	DELIVERY MILES		
448 Mills Wy #B Goleta, CA 93117	VEHICLE ID. NO. JTD...R321010104764	SELLING DEALER NO.	PRODUCTION DATE 05/01/01		
SANTA BARBARA, CA 93105	F.T.E. NO.	P.O. NO.	R.O. DATE 05/10/05		
RESIDENCE PHONE 456-3810	BUSINESS PHONE	COMMENTS			

THIS CHECK-UP IS NOT A COMPLETE CHECK OF EVERY COMPONENT OF THE VEHICLE, DEALER DOES NOT IMPLY A WARRANTY OF FITNESS FOR ANY INSPECTED OR UNINSPECTED COMPONENT OF THE VEHICLE.

TOTALS	
THANK YOU FOR BRINGING YOUR CAR TO TOYOTA OF SANTA BARBARA..	TOTAL LABOR.... 327.36
IF FOR ANY REASON YOU ARE NOT SATISFIED WITH OUR CUSTOMER	TOTAL PARTS.... 235.47
SERVICE PLEASE CONTACT US PROMPTLY. YOUR SATISFACTION IS OUR	TOTAL SUBLET... 0.00
MAIN GOAL.....	TOTAL G.O.G.... 14.00
OUR RESPONSIBILITY IS TO BE SURE YOU REACH YOUR DESTINATION	TOTAL MISC CHG. 0.00
WITH CONFIDENCE.....	TOTAL MISC DISC 0.00
DOUG, TONY, AND MATT	TOTAL TAX..... 19.33
	TOTAL INVOICE \$ 596.16

CUSTOMER SIGNATURE



"I love what you do for me."

PAID

MAY 12 2005

Per